

OLD SACRAMENTO
RIVERFRONT EMBARCADERO
AND K STREET BARGE
REPAIR PROJECT # PB15-030

APPENDIX

A


SITE PHOTOS



K Street Section of Project.



Downstream (south) Section of Project.



Existing Wood Deck on the Embarcadero with Protruding Bolts.



Shade Structure on the Embarcadero Showing Bolted Vertical Supports.



Existing Concrete Floodwall with Timber Fascia and Cap.



Timber Beam that Forms the Floodwall on the Elevated Embarcadero Sections.



View of the Gangway and the Barge Facilities adjacent to the Delta King.



Current Condition of the Stairs.



Hoistway Housing.



Joe's Crab Shack.