

## **Appendix J**

### **Photo Log**

**Photos of the July 11<sup>th</sup>, 2024 Site Visit and Field Survey of the Project Area**



**Photo 1: Cotton Lane entrance into the southeastern corner of the Project area off of West Stockton Blvd. with the Project area to the left within the open grassland area.**



**Photo 2: Eastern section of the Project area off of West Stockton Blvd. with the subject parcel located within the open grassland area. Cotton Lane entrance to the left.**





**Photo 3: Southern section of the Project area off of Cotton Lane to the right. Photo looking from southwestern section of the Project area to the center of the Project area.**



**Photo 4: From southwestern corner of the Project area looking north. Project area is dominated by non-native annual grassland. No wetlands or streams present.**





**Photo 5: Looking towards the southeastern section of the Project area. State Route 99 in photo east of West Stockton Blvd. and the Project area.**



**Photo 6: Northeastern corner of the Project area with West Stockton Blvd. to the left. City of Sacramento stormwater maintenance drain with Project area ahead and to the right.**





**Photo 7: Photo looking west along the northern border of the Project area along a City of Sacramento bike trail. Photo from the southeastern corner of the Project to the left.**



**Photo 8: Cotton Lane is an existing gravel access road along the southern edge of the Project area to the left. Project area is disturbed and dominated by grassland habitat.**





**Photo 9: Photo looking southwest from the northern section of the Project area. Project area is dominated entirely of non-native annual grassland. No wetlands present.**



**Photo 10: Looking south/southwest into the Project area. Project area includes disturbance and non-native annual grassland. No streams or wetlands present.**